

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

U.S. Naval Asylum, Biddle Hall
(U.S. Naval Home, Biddle Hall)
Southwest corner Gray's Ferry Avenue and
Twenty-fourth Street
Philadelphia
Philadelphia County
Pennsylvania

HABS No. PA-1622 A

Jack E. Boucher, photographer 1964

- PA-1622 A-1 GENERAL VIEW AND EAST (FRONT) FACADE, FROM SOUTHEAST
- PA-1622 A-2 MAIN ENTRANCE PORTICO AND STAIRWAY, EAST ELEVATION
- PA-1622 A-3 REAR ELEVATION (WEST), FROM SOUTHWEST
- PA-1622 A-4 DETAIL OF FRONT VERANDAS, WEST (LEFT) WING, FROM SOUTHEAST. NOTE
PIERS IN RAISED BASEMENT, ETC.
- PA-1622 A-5 DETAIL OF VERANDAS, WEST WING, LOOKING SOUTHWEST
- PA-1622 A-6 IRON FENCE SEPARATING GRAY'S FERRY AVENUE AND NAVAL GROUNDS.
FENCE IS ORIGINAL-- NOTE GREEK ACROTERRANS.
- PA-1622 A-7 MAIN STAIRWAY, PRINCIPAL STORY, LOOKING NORTH
- PA-1622 A-8 CHAPEL, IN REAR OF CENTER SECTION. NOTE DOME. LOOKING NORTHWEST
- PA-1622 A-9 SAME AS PA-1622 A-8.
- PA-1622 A-10 FIRST FLOOR NORTH CORRIDOR LOOKING NORTH
- PA-1622 A-11 FIRST FLOOR FIREPLACE. NOTE IONIC COLUMNS AND CORNER BLOCKS
- PA-1622 A-12 STAIRWAY DETAIL, STONE TREAD
- PA-1622 A-13 ATTIC DOME OVER CHAPEL, DETAIL OF BRICK STRUCTURE

PHOTOCOPIES

- PA-1622 A-14 PLOT MAP OF THE NAVAL ASYLUM. NOTE ABSENCE OF LATER
BUILDINGS. SURVEYED 1836 BY RANDAL H. RICKEY
- PA-1622 A-15 PLOT MAP OF THE NAVAL ASYLUM, CA. 1844. NOTE THE PRESENCE OF
OF GOVERNOR'S RESIDENCE (to right of Biddle Hall) AND SURGEON'S
RESIDENCE

(Continued on page 2)

- PA-1622 A-16 PLOT MAP OF THE ASYLUM, 1878. NOTE ADDITION OF OTHER BUILDINGS.
- PA-1622 A-17 BASEMENT PLAN OF EAST (RIGHT SIDE) WING. SKETCHED BY WILLIAM STRICKLAND, 1826
- PA-1622 A-18 BASEMENT PLAN OF WEST (LEFT SIDE) WING, SKETCHED BY WILLIAM STRICKLAND, 1826.
- PA-1622 A-19 PRINCIPAL STORY PLAN OF EAST (RIGHT SIDE) WING, SKETCHED BY WILLIAM STRICKLAND, 1826
- PA-1622 A-20 PRINCIPAL STORY PLAN OF WEST (LEFT SIDE) WING, SKETCHED BY WILLIAM STRICKLAND, 1826
- PA-1622 A-21 SECOND STORY PLAN OF EAST (RIGHT SIDE) WING, SKETCHED BY WILLIAM STRICKLAND, 1826
- PA-1622 A-22 SECOND STORY PLAN OF WEST (LEFT SIDE) WING, SKETCHED BY WILLIAM STRICKLAND, 1826
- PA-1622 A-23 JULY 6, 1843 DRAWINGS SHOWING ADDITION OF CELLAR

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO

U. S. NAVAL ASYLUM, BIDDLE HALL

HABS No. PA-1622-A

Grays Ferry Avenue at Twenty-fourth Street
Philadelphia
Independent City
Pennsylvania

Photographs HABS No. PA-1622-A-1 to PA-1622-A-23 were transmitted previously to the Library of Congress.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Lewis Tanner, Photographer, April 2003

PA-1622-A-24	GENERAL VIEW FROM THE NORTHEAST.
PA-1622-A-25	GENERAL VIEW FROM THE NORTHEAST.
PA-1622-A-26	EAST (PRINCIPAL) ELEVATION, TAKEN ACROSS GRAY'S FERRY AVENUE.
PA-1622-A-27	CENTRAL PAVILION WITH OCTASTYLE IONIC PORTICO, EAST ELEVATION.
PA-1622-A-28	PERSPECTIVE VIEW FROM THE SOUTHEAST.
PA-1622-A-29	PERSPECTIVE VIEW, SOUTH WING, FROM THE SOUTHEAST (NOTE THE MONITOR RUNNING ALONG THE RIDGELINE, PROVIDING NATURAL LIGHT ALONG THE THIRD-FLOOR MAIN CORRIDOR).
PA-1622-A-30	SOUTH WALL OF SOUTH WING TERMINATING PAVLION, FROM THE SOUTHEAST.
PA-1622-A-31	OBLIQUE VIEW, EAST ELEVATION, FROM THE SOUTHEAST (NOTE THE MISSING PORTICO ROOF).

U. S. NAVAL ASYLUM, BIDDLE HALL
HABS No. PA-1622-A
INDEX TO PHOTOGRAPHS
(Page 2)

- PA-1622-A-32 PERSPECTIVE VIEW FROM THE SOUTHWEST. THIS VIEW CAPTURES THE VERANDAH TIERS AT THE "BACK" OF THE BUILDING. THE PORTION TO THE LEFT IS THE WING EXTENDING WESTWARD FROM THE ENTRANCE PORTICO ON THE EAST, WHICH CONTAINS THE ROTUNDA. THE LARGE CONCRETE BLOCK SECTION AT RIGHT IS ONE OF TWO FIRE TOWERS THAT WERE CONSTRUCTED IN 1953.
- PA-1622-A-33 WEST WALL OF ROTUNDA EXTENSION. THE ROTUNDA IS POSITIONED BEHIND THE CENTRAL ASHLAR-COURSED STONE SECTION. ROOMS FLANKING THE ROTUNDA ARE BOUNDED BY THE VERANDAHs.
- PA-1622-A-34 VIEW OF THE ROTUNDA EXTENSION AND WEST WALL OF THE NORTH WING FROM THE NORTH. THE DAMAGE VISIBLE IN THE PHOTOGRAPH RESULTED FROM BOTH GENERAL NEGLECT AND A DESTRUCTIVE FIRE IN FEBRUARY 2003 SET BY ARSONISTS.
- PA-1622-A-35 VIEW OF THE NORTH WING AND CENTRAL ROTUNDA FROM THE NORTHWEST.
- PA-1622-A-36 VIEW OF THE NORTH WING AND ROTUNDA EXTENSION FROM THE NORTHWEST. THE LARGE CONCRETE BLOCK SECTION AT LEFT IS ONE OF TWO FIRE TOWERS THAT WERE CONSTRUCTED IN 1953.
- PA-1622-A-37 NORTH WALL OF THE NORTH WING, FROM THE NORTHWEST.
- PA-1622-A-38 VIEW OF THE NORTH WING FROM THE NORTHEAST. THE ROOF AND THIRD-FLOOR ARE MOSTLY DESTROYED BECAUSE OF THE 2003 FIRE.
- PA-1622-A-39 DETAIL VIEW, EAST WALL OF NORTH WING CLEARLY SHOWING THE DAMAGE INCURRED DURING THE 2003 FIRE.
- PA-1622-A-40 DETAIL VIEW, ENTRANCE PORTICO FROM THE SOUTH.
- PA-1622-A-41 SOUTH WING ROOF FROM THE SOUTH LOOKING TOWARD CENTER CITY PHILADELPHIA (NOTE THE THIRD-FLOOR MONITOR ON THE LEFT AND DAMAGE TO THE ROOF OVER THE CENTRAL PAVILION).

U. S. NAVAL ASYLUM, BIDDLE HALL
HABS No. PA-1622-A
INDEX TO PHOTOGRAPHS
(Page 3)

- PA-1622-A-42 SOUTH WING ROOF FROM THE NORTHEAST, TAKEN FROM A CHERRY PICKER. THIS VIEW IS PARTICULARLY GOOD IN CAPTURING THE MONITOR AND THE DORMERS THAT PROVIDED LIGHT AND VENTILATION FOR THE THIRD-FLOOR ROOMS. AT CENTER ARE TWO OF THE ORIGINAL STONE CHIMNEYS AND AT RIGHT CENTER IS THE ELEVATOR'S MECHANICAL PENTHOUSE. THE SEVERITY OF THE 2003 FIRE DAMAGE IS EVIDENT AT THE BOTTOM OF THE PHOTOGRAPH, CAPTURING THE CENTRAL PAVILION.
- PA-1622-A-43 VIEW OF THE CENTRAL PAVILION FROM THE EAST FROM A CHERRY PICKER. THE PEDIMENT OF THE EAST ELEVATION'S PORTICO IS EVIDENT IN THE FOREGROUND, WITH THE SURVIVING PORTIONS OF THE TOP OF THE ROTUNDA VISIBLE BEYOND AND TO THE RIGHT OF THE ELEVATOR'S MECHANICAL PENTHOUSE.
- PA-1622-A-44 PERSPECTIVE VIEW OF THE PORTICO AND NORTH WING ON THE EAST FACADE, LOOKING NORTHWEST FROM A CHERRY PICKER.
- PA-1622-A-45 INTERIOR VIEW, GROUND-FLOOR MAIN CORRIDOR LOOKING SOUTH FROM THE BUILDING'S CENTER.
- PA-1622-A-46 INTERIOR VIEW, ROOM AT SOUTHERN TERMINUS OF GROUND-FLOOR MAIN CORRIDOR, LOOKING SOUTHEAST.
- PA-1622-A-47 INTERIOR VIEW, GROUND-FLOOR ROOM IN SOUTHEAST CORNER LOOKING SOUTH. MASONRY GROIN AND BARREL VAULTING WAS USED THROUGHOUT THE BUILDING IN ATTEMPT TO "FIREPROOF" THE STRUCTURE, A MAJOR ADVANCEMENT IN THE DESIGN OF INSTITUTIONAL STRUCTURES DURING THE SECOND QUARTER OF THE NINETEENTH CENTURY.
- PA-1622-A-48 INTERIOR VIEW, REPRESENTATIVE GROUND-FLOOR RESIDENT ROOM, LOOKING WEST. THE ROOM IS LOCATED ON THE WEST SIDE OF THE SOUTH WING.

U. S. NAVAL ASYLUM, BIDDLE HALL
HABS No. PA-1622-A
INDEX TO PHOTOGRAPHS
(Page 4)

- PA-1622-A-49 INTERIOR VIEW, GROUND-FLOOR ROOM FORMERLY USED FOR BILLIARDS, LOOKING SOUTHEAST. THIS ROOM IS LOCATED ON THE EAST SIDE OF THE SOUTH WING ADJACENT TO THE CENTRAL PAVILION.
- PA-1622-A-50 INTERIOR VIEW, GROUND-FLOOR PASSAGE IN CENTRAL PAVILION, LOOKING SOUTH. THE FORWARD OPENING ACCESSES THE ELEVATOR SHAFT. THE WELL-ARTICULATED DOORWAY BEHIND LETS ONTO A SMALL VESTIBULE LOCATED ON THE WEST GROUND-FLOOR VERANDAH OF THE SOUTH WING.
- PA-1622-A-51 INTERIOR VIEW, GROUND-FLOOR PASSAGE CROSSING THE MAIN CORRIDOR AT ITS CENTER, LOOKING EAST THROUGH THE DOORWAY LINKING THE TWO PERPENDICULAR AXES. THE DOOR AT THE END OF THE PASSAGE OPENS ONTO A PASSAGE RUNNING UNDER THE ENTRANCE PORTICO BEARING GROUND-FLOOR EXTERIOR DOORS AT EACH END.
- PA-1622-A-52 INTERIOR VIEW, BARREL-VAULTED STORE ROOM OPENING FROM THE SOUTH SIDE OF THE GROUND FLOOR'S CENTRAL EAST-WEST PASSAGE (PA-1622-A-51), LOOKING NORTHEAST.
- PA-1622-A-53 INTERIOR VIEW, FROM GROUND FLOOR UP ONE OF TWO MIRROR-IMAGE STAIRWAYS IN BUILDINGS CENTRAL PAVILION. THIS ONE IS LOCATED AT THE SOUTHWESTERN CORNER OF THE CROSSING OF THE MAIN CORRIDOR AND THE CENTRAL EAST-WEST PASSAGE, LOOKING SOUTH. THE STAIRCASE IS COMPOSED OF MARBLE STEPS CANTILEVERED OUT FROM THE WALL, EACH RESTING TOP OF THE STAIR BELOW. THE DAMAGE VISIBLE IN THIS PHOTOGRAPH STEMMED FROM VANDALS PUSHING A PIECE OF MECHANICAL EQUIPMENT OFF THE SECOND-STORY LANDING.
- PA-1622-A-54 INTERIOR VIEW, FROM GROUND FLOOR UP THE STAIR LOCATED AT THE NORTHWESTERN CORNER OF THE CROSSING OF THE MAIN CORRIDOR AND THE CENTRAL EAST-WEST PASSAGE, LOOKING NORTH. UNLIKE THE STAIR TO THE SOUTH, THIS ONE RETAINS ITS BASIC STRUCTURAL CONFIGURATION.

U. S. NAVAL ASYLUM, BIDDLE HALL
HABS No. PA-1622-A
INDEX TO PHOTOGRAPHS
(Page 5)

- PA-1622-A-55 INTERIOR VIEW, GROUND-FLOOR DINING HALL
EXTENDING ACROSS THE ROTUNDA EXTENSION FROM
ITS NORTHERN EXTERIOR WALL TO ITS SOUTHERN
EXTERIOR WALL, FROM THE NORTH.
- PA-1622-A-56 INTERIOR VIEW, FIRST-FLOOR LOOKING WEST FROM
PRINCIPAL DOOR, ACROSS THE MAIN CORRIDOR, BACK
TO THE DOOR AND DECORATIVE FANLIGHT IN THE
ROTUNDA'S WEST WALL.
- PA-1622-A-57 INTERIOR VIEW, ROTUNDA LOOKING WEST (NOTE THE
SUNLIGHT ENTERING THROUGH THE OCULUS).
- PA-1622-A-58 INTERIOR VIEW, ROTUNDA DOME AND OCULUS,
FROM THE SOUTHEAST.
- PA-1622-A-59 INTERIOR VIEW, FIRST-FLOOR ROOM CONNECTING
WITH THE ROTUNDA THROUGH THE DOOR AT THE
CENTER OF ITS SOUTH WALL AND EXTENDING
THROUGH TO THE SOUTH EXTERIOR WALL OF THE
ROTUNDA EXTENSION, FROM THE NORTH.
- PA-1622-A-60 INTERIOR VIEW, NORTH STAIR LOOKING SOUTH FROM
LANDING BETWEEN FIRST AND SECOND FLOORS.
- PA-1622-A-61 INTERIOR VIEW, NORTH STAIR LOOKING SOUTHWEST
FROM THE SECOND-FLOOR LANDING.
- PA-1622-A-62 INTERIOR VIEW, REPRESENTATIVE FIRST-FLOOR
RESIDENT ROOM, LOCATED NEAR THE MIDDLE OF THE
SOUTH WING ON THE EAST SIDE, LOOKING WEST. THE
CLERESTORY WINDOW LOCATED ABOVE THE DOOR
FACILITATED BETTER VENTILATION AND ADMITTED A
DEGREE OF NATURAL LIGHT TO THE WINDOWLESS
MAIN CORRIDOR (NOTE THE BULL'S EYE CORNER
BLOCKS OF THE GREEK REVIVAL ARCHITRAVE
MOLDING AROUND THE DOORWAY ACROSS THE
CORRIDOR).
- PA-1622-A-63 INTERIOR VIEW, FIRST-FLOOR PASSAGE IN CENTRAL
PAVILION LOOKING NORTH. THE ARCHED OPENING
AT THE END OF THE PASSAGE ORIGINALLY LET ONTO
THE WEST VERANDAH OF THE NORTH WING.

U. S. NAVAL ASYLUM, BIDDLE HALL
HABS No. PA-1622-A
INDEX TO PHOTOGRAPHS
(Page 6)

- PA-1622-A-64 INTERIOR VIEW, FIRST-FLOOR ROOM EXTENDING BETWEEN THE NORTH WALL OF THE ROTUNDA AND THE ROTUNDA EXTENSION'S NORTH EXTERIOR WALL, LOOKING SOUTHWEST. THE SMALL DOORWAY AT CENTER OPENS ONTO THE VESTIBULE LETTING ONTO THE ROTUNDA.
- PA-1622-A-65 SECOND-STORY VERANDAH ON THE EAST SIDE OF THE SOUTH WING, FROM THE NORTH.
- PA-1622-A-66 SECOND-STORY VERANDAH, LOOKING NORTHWEST FROM THE POINT WHERE IT TURNS NINETY DEGREES AT THE INTERSECTION OF THE SOUTH WING AND THE ROTUNDA EXTENSION. THE IRON COLUMNS AND BALUSTRADE ARE ORIGINAL TO THE STRUCTURE. THE COLUMNS MIGHT BE THE EARLIEST SYSTEMATIC USE OF STRUCTURAL IRON IN AN AMERICAN BUILDING.
- PA-1622-A-67 SECOND-STORY VERANDAH ON THE WEST SIDE OF THE SOUTH WING FROM THE VERANDAH ON THE NORTH SIDE OF THE ROTUNDA EXTENSION. THE EXTENT OF THE DESTRUCTION STEMMING FROM THE 2003 FIRE IS CLEARLY EVIDENT IN THIS PHOTOGRAPH.
- PA-1622-A-68 "DOG HOUSE" OR VESTIBULE AT THE SECOND-STORY ENTRANCE LOCATED AT THE INTERSECTION OF THE WEST VERANDAH OF THE SOUTH WING AND THE SOUTH VERANDAH OF THE ROTUNDA EXTENSION.
- PA-1622-A-69 INTERIOR VIEW, MAIN SECOND-STORY CORRIDOR, LOOKING SOUTH INTO THE SOUTH WING FROM A POINT NEAR THE CENTRAL PAVILION.
- PA-1622-A-70 INTERIOR VIEW, MAIN SECOND-STORY CORRIDOR, LOOKING NORTH FROM THE CENTRAL PAVILION INTO THE NORTH WING.
- PA-1622-A-71 INTERIOR VIEW, SECOND-STORY PASSAGE EXTENDING WESTWARD FROM MAIN CORRIDOR TO ROOMS ON THE NORTH SIDE OF THE ROTUNDA IN THE ROTUNDA EXTENSION. THE ROOF AND THIRD-FLOOR IN THIS AREA IS COMPLETELY MISSING.

U. S. NAVAL ASYLUM, BIDDLE HALL
HABS No. PA-1622-A
INDEX TO PHOTOGRAPHS
(Page 7)

- PA-1622-A-72 VIEW LOOKING NORTH THROUGH THE OPENING THAT FORMERLY CONNECTED THE SECOND-STORY VERANDAH ON THE WEST SIDE OF THE NORTH WING TO A PASSAGE IN THE ROTUNDA EXTENSION.
- PA-1622-A-73 INTERIOR VIEW, MAIN SECOND-STORY CORRIDOR, LOOKING NORTH FROM CENTRAL PAVILION INTO THE NORTH WING.
- PA-1622-A-74 INTERIOR VIEW, SECOND-STORY RESIDENT ROOM ON WEST SIDE OF CENTRAL PAVILION ADJACENT TO THE DOORS INTO THE SOUTH WING, LOOKING WEST.
- PA-1622-A-75 INTERIOR VIEW, SECOND-STORY PASSAGE RUNNING ALONG THE SOUTH SIDE OF THE ROTUNDA LOOKING WEST FROM THE MAIN CORRIDOR. THE OPENING TO THE LEFT ACCESSES THE ELEVATOR SHAFT.
- PA-1622-A-76 VIEW LOOKING SOUTH OUT THE DOOR OPENING FROM THE SOUTH SIDE OF THE ROTUNDA EXTENSION ONTO THE "DOG HOUSE" OR VESTIBULE POSITIONED WHERE THE WEST VERANDAH OF THE SOUTH WING TURNS NINETY DEGREES AND CONTINUES ALONG THE SOUTH WALL OF THE CENTRAL PAVILION.
- PA-1622-A-77 INTERIOR VIEW, LOOKING NORTHWARD UP THE WELL OF THE NORTH STAIR IN THE CENTRAL PAVILION.
- PA-1622-A-78 INTERIOR VIEW, PASSAGE LOCATED BETWEEN THE TWO STAIRS IN THE CENTRAL PAVILION, LOOKING WEST FROM THE MAIN CORRIDOR TO THE OCULUS OPENING ONTO THE ROTUNDA. THE OCULUS IN THE ROTUNDA'S WEST WALL IS ALSO VISIBLE.
- PA-1622-A-79 INTERIOR VIEW, SECOND-STORY ROOM LOCATED BETWEEN THE MAIN CORRIDOR AND THE EAST EXTERIOR WALL OF THE CENTRAL PAVILION, LOOKING NORTHEAST. THE WINDOW LOOKS OUT ONTO THE ENTRANCE PORTICO.
- PA-1622-A-80 INTERIOR VIEW, SECOND-STORY STOREROOM OPENING FROM THE NORTH END OF THE MAIN CORRIDOR, LOOKING WEST. THE SQUARE WINDOW IN THE WEST WALL "BORROWED LIGHT" FROM AN ADJACENT PASSAGE.

U. S. NAVAL ASYLUM, BIDDLE HALL
HABS No. PA-1622-A
INDEX TO PHOTOGRAPHS
(Page 8)

- PA-1622-A-81 INTERIOR VIEW, SECOND-STORY ROOM ON WEST SIDE OF MAIN CORRIDOR IN CENTRAL PAVILION, LOOKING EAST.
- PA-1622-A-82 INTERIOR VIEW, SECOND-STORY BATHROOM LOCATED ON THE EAST SIDE OF THE MAIN CORRIDOR, LOOKING EAST. THE BATHROOM WAS A LATER INSERTION INTO A MUCH-LARGER CHAMBER AND STANDS ACROSS THE CORRIDOR FROM ROOM IN VIEW PA-1622-A-81.
- PA-1622-A-83 INTERIOR VIEW, ROOM ON NORTH SIDE OF LATER PARTITION WALL CREATING THIS SPACE AND THE ADJACENT BATHROOM TO THE SOUTH (PA-1622-A-82) (NOTE THE BRICK RELIEVING ARCH LOCATED ABOVE THE REMAINDER OF THE TRIPARTITE WINDOW POSITIONED IN THE ROOM'S EAST WALL.
- PA-1622-A-84 INTERIOR VIEW, THIS SPACE WAS ORIGINALLY TWO RESIDENT ROOMS LOCATED ON THE EAST SIDE OF THE MAIN CORRIDOR IN THE NORTH WING, LOOKING EAST. THE LINE OF THE FORMER PARTITION WALL IS INDICATED AT THE CENTER OF THE FLOOR.
- PA-1622-A-85 INTERIOR VIEW, LARGE ROOM LOCATED IN THE NORTHEAST CORNER OF THE SECOND STORY, LOOKING NORTHWEST.
- PA-1622-A-86 VIEW LOOKING NORTH ON THE THIRD-FLOOR STANDING IN WHAT HAD BEEN A RESIDENT ROOM ON THE WEST SIDE OF THE SOUTH WING. THIS PHOTOGRAPH WAS TAKEN AFTER THE HEAVILY FIRE-DAMAGED ROOFING AND ROOF STRUCTURE HAD BEEN REMOVED.
- PA-1622-A-87 VIEW LOOKING SOUTH ON THE THIRD FLOOR FROM A SPACE IN THE ROTUNDA EXTENSION NEAR THE ELEVATOR TOWER. THIS PHOTOGRAPH CAPTURES THE FIRE DAMAGE ON THE WEST SIDE OF THE SOUTH WING PRIOR TO THE REMOVAL OF FRAMING AND DEBRIS, AS WELL AS THE MANNER IN WHICH THE ORIGINAL ROOF TRUSSES WERE SUPPORTED BY THE IRON VERANDAH COLUMNS.

U. S. NAVAL ASYLUM, BIDDLE HALL
HABS No. PA-1622-A
INDEX TO PHOTOGRAPHS
(Page 9)

PA-1622-A-88	SIMILAR VIEW TO PA-1622-A-87, BUT WITH THE BURNED TIMBERS REMOVED AND THE STRUCTURE STABILIZED.
PA-1622-A-89	VIEW LOOKING WEST DOWN A THIRD-FLOOR PASSAGE ON THE SOUTH SIDE OF THE ROTUNDA EXTENSION FROM THE MAIN CORRIDOR. THE ELEVATOR OPENING IS TO THE LEFT AND THE WINDOW ON THE RIGHT LOOKS DOWN THE SOUTH STAIR IN THE CENTRAL PAVILION.
PA-1622-A-90	VIEW LOOKING NORTH THROUGH THIRD-FLOOR WINDOW OVERLOOKING THE SOUTH STAIR OF THE CENTRAL PAVILION.
PA-1622-A-91	THIRD-FLOOR VIEW LOOKING WEST THROUGH AN OPENING AT THE END OF THE PASSAGE CAPTURED IN PA-1622-A-89.
PA-1622-A-92	VIEW INTO FORMER THIRD-FLOOR ROOM IN THE SOUTHERN PORTION OF THE ROTUNDA EXTENSION, LOOKING WEST THROUGH OPENING IN PA-1622-A-91.
PA-1622-A-93	THIRD-FLOOR VIEW LOOKING EAST FROM THE ELEVATOR LANDING WHERE IT INTERSECTS WITH THE MAIN CORRIDOR.
PA-1622-A-94	THIRD-FLOOR VIEW LOOKING SOUTH FROM THE NORTH WING ALONG WHAT HAD BEEN THE MAIN CORRIDOR, AFTER DEMOLITION AND STABILIZATION.
PA-1622-A-95	THIRD-FLOOR VIEW LOOKING SOUTH FROM THE NORTH WING ALONG WHAT HAD BEEN THE MAIN CORRIDOR, AFTER DEMOLITION AND STABILIZATION.
PA-1622-A-96	THIRD-FLOOR VIEW LOOKING NORTH IN THE NORTH WING ALONG WHAT HAD BEEN THE MAIN CORRIDOR, AFTER DEMOLITION AND STABILIZATION.
PA-1622-A-97	THIRD-FLOOR VIEW LOOKING NORTH INTO THE TERMINATING PAVILION OF THE NORTH WING AFTER REMOVAL OF DEBRIS.
PA-1622-A-98	VIEW LOOKING NORTH INTO THE TERMINATING PAVILION OF THE NORTH WING BEFORE REMOVAL OF DEBRIS.

U. S. NAVAL ASYLUM, BIDDLE HALL
HABS No. PA-1622-A
INDEX TO PHOTOGRAPHS
(Page 10)

PA-1622-A-99	VIEW LOOKING SOUTH FROM THE TERMINATING PAVILION OF THE NORTH WING BEFORE THE REMOVAL OF DEBRIS.
PA-1622-A-100	THIRD-FLOOR VIEW LOOKING EAST TOWARD GRAY'S FERRY AVENUE FROM THE EAST SIDE OF THE NORTH WING.
PA-1622-A-101	VIEW LOOKING SOUTH FROM WHAT HAD BEEN A RESIDENT ROOM ON THE EAST SIDE OF THE NORTH WING. THIS VIEW CAPTURES THE ROOFLESS STATE OF THE PORTICO.
PA-1622-A-102	VIEW LOOKING SOUTHWEST FROM WHAT HAD BEEN A THIRD-FLOOR RESIDENT ROOM ON THE WEST SIDE OF THE NORTH WING.
PA-1622-A-103	VIEW LOOKING NORTH FROM THE THIRD-FLOOR OF THE CENTRAL PAVILION. THE ARCHED OPENING ONCE PROVIDED ACCESS TO THE VERANDAH ON THE WEST SIDE OF THE NORTH WING ON THE SECOND STORY.
PA-1622-A-104	VIEW LOOKING NORTH ALONG THE MAIN CORRIDOR ON THE THIRD FLOOR OF THE SOUTH WING. THIS VIEW, BEFORE THE DAMAGED ROOF WAS REMOVED, CAPTURES THE MANNER IN WHICH THE CONTINUOUS ROOF MONITOR PROVIDED NATURAL ILLUMINATION AND VENTILATION FOR THE THIRD-FLOOR.
PA-1622-A-105	VIEW LOOKING SOUTH ALONG THE MAIN CORRIDOR ON THE THIRD FLOOR OF THE SOUTH WING. THE OPENINGS ALONG THE TOP OF THE CORRIDOR WALLS ALLOWED FOR THE MOVEMENT OF AIR AND LIGHT BETWEEN THE CORRIDOR AND THE RESIDENT ROOMS.
PA-1622-A-106	VIEW LOOKING NORTH FROM THE MIDDLE OF THE MAIN CORRIDOR ON THE THIRD FLOOR OF THE SOUTH WING AFTER REMOVAL OF THE MONITOR.
PA-1622-A-107	VIEW LOOKING NORTH FROM THE MIDDLE OF THE MAIN CORRIDOR ON THE THIRD FLOOR OF THE SOUTH WING AFTER REMOVAL OF THE MONITOR.

U. S. NAVAL ASYLUM, BIDDLE HALL
HABS No. PA-1622-A
INDEX TO PHOTOGRAPHS
(Page 11)

PA-1622-A-108	VIEW LOOKING NORTH ALONG THE MAIN CORRIDOR ON THE THIRD FLOOR OF THE CENTRAL PAVILION. THE OPENING ON THE NEAR LEFT LOOKS DOWN INTO THE SOUTH STAIRWELL OF THE CENTRAL PAVILION.
PA-1622-A-109	VIEW LOOKING WEST FROM MAIN CORRIDOR INTO WHAT HAD BEEN TWO RESIDENT ROOMS ON THE WEST SIDE OF THE SOUTH WING.
PA-1622-A-110	VIEW LOOKING NORTHEAST IN MAIN CORRIDOR INTO A FORMER RESIDENT ROOM ON THE EAST SIDE OF THE SOUTH WING.
PA-1622-A-111	VIEW LOOKING EAST INTO RESIDENT ROOM ON EAST SIDE OF SOUTH WING AFTER THE DORMER WINDOW WAS REMOVED.
PA-1622-A-112	VIEW LOOKING EAST INTO RESIDENT ROOM ON EAST SIDE OF SOUTH WING WITH DORMER STILL IN PLACE.
PA-1622-A-113	SEGMENT OF BRICK PERIMETER WALL EXTENDING AROUND THE NAVAL ASYLUM GROUNDS AT TWENTY-FOURTH STREET WITH GRAY'S FERRY AVENUE BRANCHING TO THE LEFT AND BAINBRIDGE STREET TO THE RIGHT, LOOKING SOUTHWEST.
PA-1622-A-114	BRICK PERIMETER WALL ALONG GRAY'S FERRY AVENUE, LOOKING NORTHWEST.
PA-1622-A-115	BRICK PERIMETER WALL AND NORTH GATE LODGE, LOOKING WEST.
PA-1622-A-116	CLOSER VIEW OF NORTH GATE LODGE, LOOKING NORTHWEST.
PA-1622-A-117	CLOSER VIEW OF NORTH GATE LODGE, LOOKING NORTHEAST.
PA-1622-A-118	STONE WALL AND ORNAMENTAL IRON FENCE EXTENDING ALONG GRAY'S FERRY AVENUE BETWEEN THE NORTH AND SOUTH GATE LODGES, LOOKING SOUTHWEST.
PA-1622-A-119	DETAIL VIEW, SECTION OF STONE WALL AND ORNAMENTAL IRON FENCE, LOOKING WEST.

U. S. NAVAL ASYLUM, BIDDLE HALL
HABS No. PA-1622-A
INDEX TO PHOTOGRAPHS
(Page 12)

PA-1622-A-120	BRICK PERIMETER WALL ALONG GRAY'S FERRY AVENUE AND SOUTH GATE LODGE, LOOKING NORTHWEST.
PA-1622-A-121	CLOSER VIEW OF SOUTH GATE LODGE, LOOKING SOUTHEAST.
PA-1622-A-122	VIEW OF SOUTH GATE AND GATEWAY, LOOKING WEST.
PA-1622-A-123	GENERAL VIEW OF LAWN ON THE EAST SIDE OF BIDDLE HALL, FROM ITS SOUTH END LOOKING NORTHEAST.
PA-1622-A-124	VIEW OF THE LAWN FROM THE ENTRANCE PORTICO STAIRS OF BIDDLE HALL LOOKING EAST.
PA-1622-A-125	VIEW OF LAWN ON ITS NORTH SIDE, LOOKING SOUTH.
PA-1622-A-126	DETAIL VIEW, ROOFING MATERIAL REMOVED FROM FIRE-DAMAGED ROOF AND PLACED ON LAWN TO THE EAST OF BIDDLE HALL.
PA-1622-A-127	GENERAL VIEW OF GROUNDS ON THE WEST SIDE OF BIDDLE HALL INCLUDING ONE OF THE TWO EXTANT PAVILIONS, LOOKING NORTH.
PA-1622-A-128	CLOSER VIEW OF NORTH PAVILION, LOOKING SOUTHWEST.
PA-1622-A-129	GENERAL VIEW OF GROUNDS ON WEST SIDE OF BIDDLE HALL INCLUDING ONE OF TWO EXTANT PAVILIONS, LOOKING SOUTH.
PA-1622-A-130	SOUTH PAVILION LOCATED TO THE WEST OF BIDDLE HALL, LOOKING SOUTHWEST.
PA-1622-A-131	CLOSER VIEW OF SOUTH PAVILION, LOOKING NORTH.
PA-1622-A-132	DETAIL VIEW, SOUTH PAVILION AND LANDSCAPE BEYOND, LOOKING NORTHWEST.

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO

U. S. NAVAL ASYLUM

Gray's Ferry Avenue at Twenty-fourth Street

Philadelphia

Philadelphia County

Pennsylvania

HABS No. PA-1622-A

(Page 15)

Photographs HABS Nos. PA-1622-A-1 through PA-1622-A-132 were transmitted previously to the Library of Congress.

INDEX TO BLACK AND WHITE PHOTOGRAPHS

Jack E. Boucher, Photographer, April 24, 2003.

- | | |
|---------------|---|
| PA-1622-A-133 | AERIAL VIEW, LOOKING NORTHEAST. |
| PA-1622-A-134 | AERIAL VIEW, LOOKING NORTH. |
| PA-1622-A-135 | AERIAL VIEW, LOOKING NORTHWEST. |
| PA-1622-A-136 | AERIAL VIEW. THE DESTRUCTION OF BIDDLE HALL'S ROOF OCCURRED DURING AN EARLY MORNING FIRE ON FEBRUARY 3, 2003, CONCLUDED TO BE THE WORK OF ARSONISTS. THE ROOF HAS SINCE BEEN REPLACED AND THE STRUCTURE RECONFIGURED BY TOLL BROTHERS RESIDENTIAL DEVELOPERS FOR CONDOMINIUM UNITS. |
| PA-1622-A-137 | AERIAL VIEW, LOOKING SOUTHWEST. |

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

ADDENDUM TO:

HABS PA-1622-A

U. S. NAVAL ASYLUM, BIDDLE HALL

(U. S. Naval Home)

Gray's Ferry Avenue

Philadelphia

Philadelphia County

Pennsylvania

Photographs No. HABS PA-1622-A-1 through HABS PA-1622-1-137 were previously transmitted to Library of Congress.

INDEX TO COLOR TRANSPARENCIES

Jack E. Boucher, photographer

PA-1622-A-138 (CT)	DETAIL OF FRONT VERANDAS, WEST (LEFT) WING, FROM SOUTHEAST SHOWING ENTRANCE PORTICO, NOTE PIERS IN RAISED BASEMENT
--------------------	--